




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD,

- 1 - A 960500 NU
- 2 - A 860700 NU
- 3 - A 963298 NU
- 4 - A 961760 XX
- 5 - A 860899 NU
- 6 - A 961649 NU
- 7 - A 860946 XX
- 8 - B 961984 XX
- 9 - B 961951 NU
- 10 - A 961168 AA
- 11 - A 961462 AA
- 12 - A 6677 XX



	P	bar			Q (3 bar)
	T	°C			l/min 29






Ideal Standard

CERALIFE O

11.2024 / B565439

B E022 ..



Ideal Standard International NV
Corporate Village – Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium
<https://www.idealstandard.com>

